



## HELMET MAINTENANCE

YOUR GEEKO WILL LAST A LONG TIME IS PROPERLY MAINTAINED

### 01 USE A STORAGE BAG

Using a padded bag for storage and transit will help to prevent scratches & blemishes

### 02 RINSE IN FRESH WATER

Rinse after each use because salt water is corrosive and salt crystals buildup

### 03 GREASE THE STUDS

Use petroleum jelly to grease the studs on your helmet periodically.

### 04 DEFLATE THE LINER BEFORE USE

To avoid over-flexing the helmet when you put it on, always inflate it on your head

### 05 STORE WITH VISOR DETACHED

This will enable the studs to dry out between each helmet use

### 06 STORE IN COOL DRY PLACE

Avoid storing your Gecko in very hot, very cold or very humid places.